

General Information

Inspection Date: 09/19/2007
 Company Name Your Company Name Here
 Company Address 123 Main St
 Apt 4
 City Montgomery State IL Zip 35487

VIN: 123XYZ456ABC789
 Vehicle Make: Chrysler
 Vehicle Year: 2004
 Vehicle Model: PT Cruiser - Touring
 Body Style: Station Wagon
 Body Color: Silver
 Interior Color: Grey
 Pictures:

Mileage: 32,345
 Engine: 4 Cyl-Turbo
 Transmission: 4 Speed Automatic
 Drive: FWD RWD 4x4 AWD



Exterior

**Key: 5=Excellent Condition 4=Good Condition 3=Fair Condition 2=Poor Condition 1=Very Poor Condition 0=Damaged Beyond Repair*

Body

Front: 4	Right Front: 5
Right Doors: 5	Right Rear: 5
Rear: 5	Left Rear: 3
Left Doors: 5	Left Front: 5
Hood: 4	Roof: 5
Bumpers: 4	Trim: 5
Overall Condition of Paint: 5	

Glass

Windshield: 2	Right Front Window: 5
Right Rear Window: 5	Rear Window: 5
Left Rear Window: 5	Left Front Window: 5

Wipers

Front Wipers: 4 Front Wiper Blades: 2	
Front Windshield Washer: 5	
	Rear Windshield Washer: 5
	Rear Wiper Blades: 4
	Rear Wipers: 5

Details: Needs front wiper blades.

Tire and Wheels

Condition of Tires: 4	Condition of Wheels: 4
-----------------------	------------------------

Exterior Avg. Score: 4.44

Interior

**Key: 5=Excellent Condition 4=Good Condition 3=Fair Condition 2=Poor Condition 1=Very Poor Condition 0=Damaged Beyond Repair*

Trunk

Spare Tire: 5

Tools: 5

Floor Pan: 5

Carpeting: 4

Jack: 5

Electrical System

Headlights: 5

Taillights: 5 Brake Lights: 5

Parking Lights: 5

Turn Signals: 5

Electric Seats: 5

Electric Windows: 5

Under Hood

Oil Leaks: 3

Exhaust Smoke: 5

Details: Leaks around valve cover.

Exhaust Leaks: 5

Interior Items:

Glove Box: 4

A/C Cooling Performance: 5

Heater Operation: 5

Hood Release: 5

Cigarette Lighter: 5

Details: Lighted vanity mirrors.

Head Rests: 4

Door Panels: 4

Dash Pad: 5

Vanity Mirrors: 5

Gauges:

Speedometer: 5

Tachometer: 5

Temperature: 5

Audio System

Radio: 5

CD Player: 5

Carpet and Upholstery:

Front Seats: 4

Headliner: 3

Rear Carpeting: 4

Rear Seats: 5

Front Carpeting: 2

Interior Avg. Score: 4.61

Final Comments on Interior: Shows some signs of wear.

Road Test Findings

**Key: 5=Excellent Condition 4=Good Condition 3=Fair Condition 2=Poor Condition 1=Very Poor Condition 0=Damaged Beyond Repair*

Road Test

Brake System-Noise, Vibration, Effort: 2
 Suspension-Performance, Noise, Rough: 5
 Idle: 4
 Engine Noise: 5
 Acceleration: 5
 Horn: 5
 Wind Noise: 3
 Starting: 3
 Details: Wind leak around left front window.

Steering Effort: Drifting Right or Left: 5
 Transmission Shift Quality, Smoothness, Effort, Slippage: 5
 Engine Operating Temperature: 5
 Transmission/Transaxle Noise: 5
 CV Joint/Drive Axle Noise: 5
 Parking Brake Operation: 4
 Engine Performance: 4

Additional Inspection Points

Door Handles: 5
 Gas Door: 5

Door Locks: 5
 Gas Cap: 5
 Evidence of Smoke Odor: 5
 Grille: 4

Tailgate/Liftgate: 5

Keyless Entry: 5

Sunroof: 5
 Fog Lamps: 5

Road Test Avg. Score: 4.55

Final Comments on Road Test: Drives well.

Overall Inspection Score Average: 4.54

**Key: 5=Excellent Condition 4=Good Condition 3=Fair Condition 2=Poor Condition 1=Very Poor Condition 0=Damaged Beyond Repair*