

General Information

Inspection Date: 09/19/2007
 Company Name Your Company Name Here
 Company Address 123 Main St
 Apt 4
 City Montgomery State IL Zip 35487

VIN: 1234XYZ456ABC789
 Vehicle Make: Chrysler
 Vehicle Year: 2004
 Vehicle Model: PT Cruiser - Touring
 Body Style: Station Wagon
 Body Color: Silver
 Interior Color: Grey
 Pictures:

Mileage: 32,345
 Engine: 4 Cyl-Turbo
 Transmission: 4 Speed Automatic
 Drive: FWD RWD 4x4 AWD



Exterior

**Key: 5=Excellent Condition 4=Good Condition 3=Fair Condition 2=Poor Condition 1=Very Poor Condition 0=Damaged Beyond Repair*
 E = Excellent Condition, G = Good Condition, F = Fair Condition, P = Poor Condition, VP = Very Poor Condition, D = Damaged Beyond Repair

E G F PVPD

Body

- Front:
- Right Front:
- Right Doors:
- Right Rear:
- Rear:
- Left Rear: Paint scraped on bumper extension.
- Left Doors:
- Left Front:
- Hood: Small dent in left edge of hood.
- Roof:
- Bumpers:
- Trim:
- Overall Condition of Paint:

Glass

- Windshield:
- Right Front Window:
- Right Rear Window:
- Rear Window:
- Left Rear Window:
- Left Front Window:

Wipers

- Front Wipers:
- Front Wiper Blades: Blades need to be replaced.
- Front Windshield Washer:
- Rear Wipers:
- Rear Wiper Blades:
- Rear Windshield Washer:

Tire and Wheels

- Condition of Tires: Normal wear for mileage shown.
- Condition of Wheels: Aluminum Wheels, need to be cleaned.

Exterior Avg. Score: 4.37

Interior

*Key: 5=Excellent Condition 4=Good Condition 3=Fair Condition 2=Poor Condition 1=Very Poor Condition 0=Damaged Beyond Repair

E = Excellent Condition, G = Good Condition, F = Fair Condition, P = Poor Condition, VP = Very Poor Condition, D = Damaged Beyond Repair

E G F PVPD

Trunk

- Spare Tire:
- Carpeting: Dirty
- Tools:
- Jack:
- Floor Pan:

Electrical System

- Headlights:
- Turn Signals:
- Taillights:
- Electric Windows:
- Brake Lights:
- Electric Seats:
- Parking Lights:

Under Hood

- Oil Leaks: Valve cover leaks.
- Exhaust Leaks:
- Exhaust Smoke:

Interior Items:

- Glove Box:
- Head Rests:
- A/C Cooling Performance
- Door Panels:
- Heater Operation:
- Dash Pad:
- Hood Release:
- Vanity Mirror: Lighted mirror.
- Cigarette Lighter:

Gauges:

- Speedometer:
- Tachometer:
- Temperature:

Audio System

- Radio:
- CD Player: Single CD

Carpet and Upholstery:

- Front Seats:
- Rear Seats:
- Headliner:
- Front Carpeting: Dirty
- Rear Carpeting:

Interior Avg. Score: 4.61

Final Comments on Interior: Shows some signs of wear.

Road Test Findings

**Key: 5=Excellent Condition 4=Good Condition 3=Fair Condition 2=Poor Condition 1=Very Poor Condition 0=Damaged Beyond Repair*

E = Excellent Condition, G = Good Condition, F = Fair Condition, P = Poor Condition, VP = Very Poor Condition, D = Damaged Beyond Repair

E G F PVPD

Road Test

- | | | | | | | |
|-------------------------------------|-------------------------------------|-------------------------------------|-------------------------------------|--------------------------|--------------------------|--|
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Brake System-Noise, Vibration, Effort: Brakes squeal while backing up. |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Steering Effort: Drifting Right or Left: |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Suspension-Performance, Noise, Rough: |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Transmission Shift Quality, Smoothness, Effort: |
| <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Idle: |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Engine Operating Temperature: |
| <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Engine Noise: |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Transmission/Transaxle Noise |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Acceleration: The turbo works well. |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | CV Joint/Drive Axle Noise: |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Horn: |
| <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Parking Brake Operation: |
| <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Wind Noise: Wind leak around left front window. |
| <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Engine Performance: |
| <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Starting: |

Additional Inspection Points

- | | | | | | | |
|-------------------------------------|-------------------------------------|--------------------------|--------------------------|--------------------------|--------------------------|-------------------------|
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Sunroof: |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Door Locks: |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Door Handles: |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Keyless Entry: |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Gas Door: |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Gas Cap: |
| <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Grille: |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Fog Lamps: |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Evidence of Smoke Odor: |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Tailgate/Liftgate: |

Road Test Avg. Score: 4.25

Final Comments on Road Test: Drives well.

Overall Inspection Score Average: 4.46

**Key: 5=Excellent Condition 4=Good Condition 3=Fair Condition 2=Poor Condition 1=Very Poor Condition 0=Damaged Beyond Repair*

Summary

Exterior

Windshield:
Front Wiper Blades: Blades need to be replaced.

Interior

Carpeting: Dirty

Road Test Findings

Brake System-Noise, Vibration, Effort: Brakes squeal while backing up.