



Move Up Move Down

- X General Information
- X Exterior
- X Interior
- X Road Test Findings

Exterior Not Applicable

[Disclaimer](#) [Tech Note](#)

Body

- Good Condition Front: <Note>
- Excellent Condition Right Front: <Note>
- Excellent Condition Right Doors: <Note>
- Excellent Condition Right Rear: <Note>
- Excellent Condition Rear: <Note>
- Fair Condition Left Rear: Paint scraped on bumper extension.
- Excellent Condition Left Doors: <Note>
- Excellent Condition Left Front: <Note>
- Good Condition Hood: Small dent in left edge of hood.
- Excellent Condition Roof: <Note>
- Good Condition Bumpers: <Note>
- Excellent Condition Trim: <Note>
- Excellent Condition Overall Condition of Paint: <Note>

Glass

- Poor Condition Windshield: <Note>
- Excellent Condition Right Front Window: <Note>
- Excellent Condition Right Rear Window: <Note>
- Excellent Condition Rear Window: <Note>
- Excellent Condition Left Rear Window: <Note>
- Excellent Condition Left Front Window: <Note>

Wipers

- Good Condition Front Wipers: <Note>
- Poor Condition Front Wiper Blades: Blades need to be replaced.
- Excellent Condition Front Windshield Washer: <Note>
- Good Condition Rear Wipers: <Note>
- Fair Condition Rear Wiper Blades: <Note>
- Excellent Condition Rear Windshield Washer: <Note>

Tire and Wheels